

Professional Engineering Certification
For
Tana Exploration Company LLC

Lease OCS-G 22802, Well #A-3
Main Pass Block 207
Casing & Cement Design Verification

I have reviewed the casing design for the above referenced well and verified it is appropriate for the purpose of which it is intended under the expected wellbore conditions presented to me.

Furthermore, I have reviewed the proposed cement program and procedures, and verified they are appropriate for the expected wellbore conditions presented to me.

Finally, I have verified that at least two independent tested barriers will be installed, in addition to cement for the 5-1/2" production liner.

Michael J Simon
Print Name

11-2-2011
Date

Michael J Simon
Signature

108065
License No..

Seal

